

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT	UNIT TYPE:												
Lined MSWLF	LC	ID		YW		Transfer		Compost		SLAS	X	COUNTY: CATAWBA	
Closed MSWLF	HI	W		White goods		Incin		T&P		FIRM		PERMIT NO.: SLAS 18-01	
CDLF	Tire '	%P/ ction		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE	

Date of Site Inspection: 6/4/2014 Date of Last Inspection: 12/12/2013

FACILITY NAME AND ADDRESS:

Gary & Virginia Dellinger A Sani-Can Service, Inc. 1885 Long Island Road Catawba County, NC

GPS COORDINATES: N: 35.6664 E: -81.0136

FACILITY CONTACT NAME AND PHONE NUMBER:

Gary Dellinger, Virginia Dellinger

(704) 483-5641

Email: neeley@asanican.com

FACILITY CONTACT ADDRESS:

Gary & Virginia Dellinger A Sani-Can Service, Inc. 8151 Webbs Road Denver, NC 28037

PARTICIPANTS:

Tony Gallagher, Composting and Land Application Branch Supervisor Deb Aja, NCDENR Solid Waste Section

STATUS OF PERMIT:

The active permit was issued on October 9, 2009, and shall expire on October 9, 2014.

PURPOSE OF SITE VISIT:

Partial Inspection.

STATUS OF PAST NOTED VIOLATIONS:

None.

OBSERVED DEFICIENCIES

None.

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

- 1. The inspection was conducted of operations.
- 2. The facility is permitted for land application of domestic septage (including portable toilet waste) and grease septage.
- 3. Proper signage was posted at the site entrance. The entrance was secured with a locked gate.
- 4. The all-weather access roads were maintained.
- 5. Current fields in operation; Fields numbered 2, 3, 4, and 5.

FIELD#	ACREAGE	CROP			
2	21.08	Fescue & Matua			
		grasses			
3	9.99	Switchgrass			
4	9.22	Fescue & Matua			
		grasses			
5	16.11	Fescue & Matua			
		grasses			

- 6. The recently active fields were inspected. Fields were vegetated as required. Some weeds were growing in Fields 3 and 5.
- 7. It appeared that loads were discharged and distributed in a manner that there was no standing water or septage.
- 8. Waste appeared to be evenly distributed; there was no standing liquid or soil disturbance observed.
- 9. There were no ruts greater that three inches deep observed in the soil surface.
- 10. The disposal area boundaries were clearly and accurately marked.
- 11. All septage discharges appeared to be made within the disposal area boundary in accordance with the permit conditions. There were no lateral drifts or debris observed in buffer areas.
- 12. No vectors or odors were noted during the inspection.

Please contact me if you have any questions or concerns regarding this inspection report.

Deborah Aja

Environmental Senior Specialist

ebrahApe

Regional Representative

deborah.aja@ncdenr.gov

Phone: 828-296-4702

Asheville Regional Office

2090 US Hwy 70

Swannanoa, NC 28778

Sent on June 9, 2014, to Gary and Virginia Dellinger by:	X	Email	Hand delivery	US Mail	Certified No.

EC: Tony Gallagher, Composting and Land Application Branch Supervisor Jason Watkins, Western District Supervisor Elizabeth Patterson, Composting and Land Application Branch